





Душевая кабина



P91B






A1 X1	A2 X1	A3 X1	A4 X2	A5 X2	A6 X2
A7 X2	A8 X1	A9 X1	A10 X1	A11 M4X25=2 X1	A12 X4
A13 X2	A14 X2	A15 X2	A16 X1	A17 X1	A18 X1
A19 ST4X10=8 X2	A20 X1	A21 ST4X10=4 X4	A22 X1	A23 L=1.5M X1	A24 L=1.7M X1
A25 X8	A26 ST4X10=4 X4	A27 X10	A28 X2	A29 X2	A30 X1
A31 X2	A32 X2	 M4X16=10	 M4X25=12	 ST4X40=8	 ST4X16=8
 $\phi 2.8$					






A14




A10




A23

A22



A17



A23

A30

